

# SUPERCAR LITES

## Technical Bulletin

Number	SCL_TB_005	Date	04.01.2018
Revision	001	Issuer	Mountune
<b>Mountune 003</b>			



### **Mountune Racing**

Prospect House  
Prospect Way  
Hutton  
Brentwood  
CM13 1XA

Tel: +44 (0)1277 226666  
Fax: +44(0)1277 226611  
Fax: +44(0)1277 226640 (Parts)  
Email: [sales@mountune.com](mailto:sales@mountune.com)  
[enquiries@mountune.com](mailto:enquiries@mountune.com)  
[www.mountune.com](http://www.mountune.com)

### **Revision 1**

**September 2017**

## **IMPORTANT RX2 / GRC LITES TEAM BULLETIN**

The following team bulletin is a reminder of best practice to all RX2 / GRC Lites teams regarding achieving engine oil pressure when a new (or rebuilt) engine is fitted.

**Remove the ignition coils and spark plugs**, the engine should be cranked on the starter motor, with the ignition turned off **and the throttle held at wide open throttle** to achieve oil pressure. The cranking duration should be limited to 5 second duration. If oil pressure is not achieved after 3 cranking events, please contact Mountune before taking any other action.

Following achieving oil pressure the spark plugs and coils can be refitted and the engine started.

### **Mountune Racing Contact details:**

Prospect House  
Prospect Way  
Hutton, Brentwood  
Essex, CM13 1XA  
England  
Tel: +44(0) 1277 226666  
Web: [www.mountune.com](http://www.mountune.com)  
Enquiries: [enquiries@mountune.com](mailto:enquiries@mountune.com)